

*If you are using a printed copy of this procedure, and not the on-screen version, then you **MUST** make sure the dates at the bottom of the printed copy and the on-screen version match.
The on-screen version of the Collider-Accelerator Department Procedure is the Official Version.
Hard copies of all signed, official, C-A Operating Procedures are kept on file in the C-A ESHQ Training Office, Bldg. 911A.*

C-A OPERATIONS PROCEDURES MANUAL

12.15 Setting Tandem Facility Radiation Zones

Text Page 2

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approved: _____ ***Signature on File*** _____
Collider-Accelerator Department Chairman Date

C. Carlson

12.15 Setting Tandem Facility Radiation Zones

1. Purpose

The purpose of this procedure is to define the sequence of activities required to set the Tandem Facility Radiation Zones.

2. Responsibilities

It is the responsibility of the person or persons executing this procedure to observe all safety rules.

3. Prerequisites

3.1 Tandem Operator training.

3.2 If converting to TTB Operation, the MP-7 HE Zone shall be disabled.

3.3 If converting to Target Room Operation, the MP-7 HE Zone shall be enabled.

4. Precautions

None

5. Procedure

5.1 Execute and fill out Tandem Radiation Zones Sweep Checklist when sweeping Tandem Facilities.

6. Documentation

6.1 Completed [C-A-OPM-ATT 12.15.a “Setting Tandem Facility Radiation Zones Sweep - Checklist](#) shall be filed in appropriate binder.

7. References

None

8. Attachments

8.1 Completed [C-A-OPM-ATT 12.15.a “Setting Tandem Facility Radiation Zones Sweep - Checklist](#) shall be filed in appropriate binder.